



#### AIR, NOISE AND VIBRATION MONTHLY MONITORING REPORT Number 001

Prepared By:

DDC. Project ID:		BBJ-XSP		Period Start: 11/1/22 End 11/30/22						
Project Name:		NYCDDC D&B – The Bronx Site Preparation								
DDC Pin No.:		8502021CR0004P-06P								
1) Community Air Monitoring Monthly Status Summary TWA – Time Weighted Average ug/m <sup>3</sup> - micrograms per cubic meter										
Number of Workdays in a Month	Nu	umber of Air Monitoring Days in a Month	Number of Days with Dust Concentrations above Action Concentrations by Month (100 ug/m <sup>3</sup> 15 minute TWA)		Comments					
21		21	1							
Community Air Monitoring Excursions and Corrective Actions Action Concentration =100 ug/m <sup>3</sup> 15 minute TWA above background concentration Stop Work Concentration = 150 ug/m <sup>3</sup> 15 minute TWA above background concentration										
Date: Time		laximum Dust Reading efore Corrective Action 15 Minute TWA (ug/m <sup>3</sup> )	Maximum Dust Reading After Corrective Action 15 Minute TWA (ug/m <sup>3</sup> )		Corrective Action					
11/4/2022 12:51PM		146	85		Street sweeper stopped work in that area					
Narrative Summary of Air Monitoring, Excursions and Corrective Actions: In November 2022, construction-related levels of Particulate Matter (PM) PM10 did not surpass the Daily Permissible Exposure Limits (PEL) as set by federal standards for the 8-hour Time Weighted Average (TWA) and did not cause air quality concerns to the community or onsite workers but there was one 15-minute dust reading above 100 ug/m <sup>3</sup> due to the offsite street sweeper passing the location of the street sweeper.										



AECOM-Hill JV 11/30/2022

	oels (dBA) le	Nonitoring Montl	iny Sum	inary	
Number of Workdays in a Month	Number of Noise Monitoring Days in a Month		Number of Days with Noise Levels above Action Levels by Month		Comments
21		21		0	There were no noise levels abov the 80 dBA limit.
<b>Community Noi</b> s Action Level =70 dB/ Stop Work Level = 80	4	oring Excursions	and Corr	ective Actions	
Date: Time		Maximum Noise Reading before Corrective Action (dBA)		Maximum Noise Reading after Corrective Action (dBA)	Corrective Action
Aitigation measur	es: No cor	rective actions or mit	tigation me	easures were required.	



AECOM-Hill JV

11/30/2022

3) Community Vibration Monitoring Monthly Summary Units: inches per second (in/sec)								
Number of Workdays in a Month	Number of Vibration Monitoring Days in a Month	Number of Days with Vibration Levels above Action Levels by Month	Comments					
21	30	10	Two out of eight vibration monitors (VM) had recorded a total of 12 exceedances, including outlier data. Detail information about exceedances is provided in the narrative summary section and plots.					
Community Vibration Monitoring Excursions and Corrective Actions Action Level = 0.5 in/sec above background Stop Work Level = 1.0 in/sec above background								
Date: Time	Maximum Vibration Level before Corrective Action (in/sec)	Maximum Vibration Level after Corrective Action (in/sec)	Corrective Action					
11/1/2022 10:45	0.625	0.44	This is an isolated event recorded at VM4 location. Laborers installing water misters along fence near sensor this isolated event.					
11/2/2022 10:05	0.535	0.11	This is an isolated event recorded at VM4 location. Laborers installing water misters along fence near sensor this isolated event.					
11/22/2022 17:40	0.545	N/A	Exceedance observed at VM4 was recorded during non-construction hours.					
11/25/2022 21:59	0.51	N/A	Exceedance observed at VM4 was recorded during non-construction hours.					
11/30/2022 03:23	0.57	N/A	Exceedance observed at VM4 was recorded during non-construction hours.					
11/4/2022 12:23	0.525	0.485	This is an isolated event recorded at VM5 location. Residents have access to the sensor.					
11/9/2022 22:23	0.575	N/A	Exceedance observed at VM5 was recorded during non-construction hours.					
11/11/2022 06:37	0.525	N/A	Exceedance observed at VM5 was recorded during non-construction hours.					
11/15/2022 12:34	0.91	0.11	This is an isolated event recorded at VM5 location. Residents have access to the sensor.					
11/19/2022 19:13 & 19:49	2.06	N/A	Exceedances observed at VM5 were recorded during non-construction hours.					
11/22/2022 09:25	0.6	0.02	This is an isolated event recorded at VM5 location. Residents have access to the sensor.					



Narrative Summary of Vibration Monitoring, Excursions and Corrective Actions: In November 2022, two vibration monitors had recorded exceedances. There were isolated events recorded at VM4 and VM5.

There was exceedance recorded at VM4 on November 1<sup>st</sup> and 2<sup>nd</sup>. Laborers were installing water misters along the fence located near sensor which caused the exceedances. Once completed, the readings returned to be within the project threshold afterwards.

VM5 is installed in the basement of a residential building, where third-party are able to access to the sensor. There were isolated events recorded at VM5 during baseline period as well.


Due to limit of access issue, VM8 was relocated to 740 E. 141st St and renamed as VM8A on November 16th.

#### ATTACHMENTS:

- 1 Include one map of monitoring station/locations
- 2 Include Data Plots
- 3 Include Baseline Reference


# Attachments


# **Environmental Monitoring The Bronx**






Vibration Monitor (VM) Air Monitoring Station (DM) Noise Monitoring Station (NM)








Exceedance level: 1 in/sec Warning level: 0.5 in/sec

C2202-VM1 Transverse C2202-VM1,2 Vertical C2202-VM1,3 Longitudinal






Exceedance level: 1 in/sec Warning level: 0.5 in/sec

C2202-VM2 Transverse C2202-VM2,2 Vertical C2202-VM2,3 Longitudinal






Exceedance level: 1 in/sec Warning level: 0.5 in/sec

C2202-VM3 Transverse C2202-VM3,2 Vertical C2202-VM3,3 Longitudinal






Exceedance level: 1 in/sec Warning level: 0.5 in/sec

C2202-VM4 Transverse C2202-VM4,2 Vertical C2202-VM4,3 Longitudinal






Exceedance level: 1 in/sec Warning level: 0.5 in/sec

C2202-VM5 Transverse C2202-VM5,2 Vertical C2202-VM5,3 Longitudinal






Exceedance level: 1 in/sec Warning level: 0.5 in/sec

C2202-VM6 Transverse C2202-VM6,2 Vertical C2202-VM6,3 Longitudinal






Exceedance level: 1 in/sec Warning level: 0.5 in/sec

C2202-VM7 Transverse C2202-VM7,2 Vertical C2202-VM7,3 Longitudinal






Exceedance level: 1 in/sec Warning level: 0.5 in/sec

C2202-VM8A Transverse C2202-VM8A,2 Vertical C2202-VM8A,3 Longitudinal






Exceedance level: 1 in/sec Warning level: 0.5 in/sec

C2202-VM1 Transverse C2202-VM1,2 Vertical C2202-VM1,3 Longitudinal






Exceedance level: 1 in/sec Warning level: 0.5 in/sec

C2202-VM2 Transverse C2202-VM2,2 Vertical C2202-VM2,3 Longitudinal






Exceedance level: 1 in/sec Warning level: 0.5 in/sec

C2202-VM3 Transverse C2202-VM3,2 Vertical C2202-VM3,3 Longitudinal






Exceedance level: 1 in/sec Warning level: 0.5 in/sec

C2202-VM4 Transverse C2202-VM4,2 Vertical C2202-VM4,3 Longitudinal






Exceedance level: 1 in/sec Warning level: 0.5 in/sec

C2202-VM5 Transverse C2202-VM5,2 Vertical C2202-VM5,3 Longitudinal






Exceedance level: 1 in/sec Warning level: 0.5 in/sec

C2202-VM6 Transverse C2202-VM6,2 Vertical C2202-VM6,3 Longitudinal






Exceedance level: 1 in/sec Warning level: 0.5 in/sec

C2202-VM7 Transverse C2202-VM7,2 Vertical C2202-VM7,3 Longitudinal





Exceedance level: 1 in/sec Warning level: 0.5 in/sec

C2202-VM8 Transverse C2202-VM8,2 Vertical C2202-VM8,3 Longitudinal

