



#### AIR, NOISE AND VIBRATION MONTHLY MONITORING REPORT Number 014

Prepared By: Roux / Wang Technology

DDC Project No.		BBJ-XSP		Period Start: 9/1/23 End 9/30/23		
Project Name:		NYCDDC D&B – The B	ronx Site Preparatio	n		
DDC Pin No.:	8502021CR0004P-06P					
1) Community TWA – Time Weighte ug/m <sup>3</sup> - micrograms p	' <b>Air</b> ed Av er cu	r Monitoring Weekly S /erage Ibic meter	Status Summary			
Number of Workdays in a Month	N	umber of Air Monitoring Days in a Month	Number of Days v Concentrations Action Concentra Month (100 ug/m <sup>3</sup> 15 minu	vith Dust above tions by te TWA)	Comments	
20		17	0		Dust monitoring not performed on 9/18, 9/25, or 9/29 due to rain	
Community Air Action Concentration Stop Work Concentra	Mon =10 ation	<b>Nitoring Weekly Excursi</b> 0 ug/m <sup>3</sup> 15 minute TWA above = 150 ug/m <sup>3</sup> 15 minute TWA a	ons and Corrective e background concentrat bove background conce	• Actions ion ntration		
Date: Time	N B	Aximum Dust Reading efore Corrective Action 15 Minute TWA (ug/m <sup>3</sup> )	Maximum Dust F After Corrective 15 Minute T (ug/m <sup>3</sup> )	Reading Action WA	Corrective Action	
Narrative Summary of Air Monitoring, Excursions and Corrective Actions: In September 2023, construction-related levels of Particulate Matter (PM) PM10 did not surpass the Daily Permissible Exposure Limits (PEL) as set by federal standards for the 8-hour Time Weighted Average (TWA) and did not cause air quality concerns to the community and/or onsite workers.						
2) Community Noise Monitoring Weekly Summary Units: A-weighted decibels (dBA)						
Number of Workdays in a Month		Number of Noise Monitoring Days in a Month	Number of Days w Levels above Actio by Month	ith Noise n Levels	Comments	
20		17	3		Noise monitoring not performed on 9/18, 9/25, or 9/29 due to rain. There were three instances of noise levels above the 80 dBA	



					limit that occurred on 9/1, 9/5,
Community Noise Monitoring Weekly Excursions and Corrective Actions         Action Level = 80 dBA         Stop Work Level = 80 dBA					
Date: Tim	e	Maximum Noise before Corrective (dBA)	Reading e Action	Maximum Noise Reading after Corrective Action (dBA)	Corrective Action
9/1/23 06:10	am	80.58		78.99	Noise meter #2 detected noise levels of between 80dbA and 81 dbA between 06:10am and 06:20am due to truck unloading merchandise on Concord. This work was not associated with the onsite work.
9/5/23 10:40	am	80.66		75.10	Noise meter #2 detected noise levels of between 80dbA and 81dbA between 10:40am and 10:50am due to rock blasting activities adjacent to the noise station. Blasting operations were halted, and work pace was reduced to keep noise levels below 80dbA.
9/26/23 12:50 9/26/23 01:00 9/26/23 01:10 9/26/23 01:20	) pm ) pm ) pm ) pm	80.44 81.98 76.16 80.15		70.14	Noise meter #2 detected noise levels between 80dbA and 82dbA between 12:50pm and 1:20pm, as listed here, due to rock drilling activities adjacent to the noise station. Hammering operations were modified and work pace was reduced but when noise levels didn't decrease below 80dbA, hammering work was halted in the area

Narrative Summary of Noise Monitoring, Excursions and Corrective Actions:

In September 2023, construction-related levels of noise did surpass the limits of Local Law 113 of 2005 during one occasion on 9/1/23, one occasion on 9/5/23, and three occasions on 9/26/23. The daily average was below the limits and did not cause noise concerns for the community.



AECOM-Hill JV

10/26/2023

3) Community Vibration Monitoring Monthly Summary Units: inches per second (in/sec)			
Number of Workdays in a Month	Number of Vibration Monitoring Days in a Month	Number of Days with Vibration Levels above Action Levels by Month	Comments
20	30	27	Four out of six vibration recorded a total of two hundred and eight exceedances. Three exceedances were caused by rock chopping with an excavator hoe ram. Two exceedances are isolated events, possibly due to non-construction related activities, associated with resident's activities. Ninety-eight events are not construction related; contractor confirmed that there was no work being performed in the area during the event times. One hundred and five exceedances were recorded during non-construction hours. Detailed information about exceedances is provided in the narrative summary section and plots.
Community Vibration M	onitoring Excursions and	Corrective Actions	
Action Level = 0.5 in/sec Stop Work Level = 1.0 in/	above background for VM /sec above background		
Date: Time	Maximum Vibration Level before Corrective Action (in/sec)	Maximum Vibration Level after Corrective Action (in/sec)	Corrective Action
9/19/2023 17:27 & 17:34	3.025	N/A	Exceedances observed at VM6 were recorded during non-construction hours.
9/27/2023 18:07	3.48	N/A	Exceedance observed at VM6 was recorded during non-construction hours.
9/29/2023 10:34	8.465	0.16	This is an isolated event recorded at VM6 possibly due to non-construction related activities, associated with resident's activities.
9/27/2023 14:19	0.552	0.007	This is an isolated event recorded at VM7 possibly due to non-construction related activities, associated with resident's activities.
9/1/2023 00:35 & 06:15	0.7953	N/A	Exceedances observed at VM11 were recorded during non-construction hours.
9/1/2023 07:35, 08:00, & 08:10	0.6988	0.2979	Exceedances observed at VM11 were due to rock chopping with an excavator hoe ram. The intensity of the hoe ram on the excavator was lower post-events.
9/5/2023 09:01, 12:35, & 14:14	0.5685	N/A	Exceedances observed at VM11 were not construction related, it is confirmed that no work was being performed in the area.
9/5/2023 15:49, 17:05, 19:00, & 19:35	0.5443	N/A	Exceedances observed at VM11 were recorded during non-construction hours.
9/6/2023 00:50, 05:50, & 06:55	0.7072	N/A	Exceedances observed at VM11 were recorded during non-construction hours
9/6/2023 08:15 to 11:33	0.6458	N/A	Exceedances observed at VM11 were not construction related, it is confirmed that no work was being performed in the area.
9/6/2023 14:25 & 14:45	0.5806	N/A	Exceedances observed at VM11 were not construction related, it is confirmed that no



## AECOM-Hill JV

10/26/2023

			work was being performed in the area.
			Exceedances observed at VM11 were
9/6/2023 16:25 & 17:25	0.5511	N/A	recorded during non-construction hours.
0/7/2022 02:10			Exceedance observed at VM11 was
9/7/2023 03:10	0.5545	N/A	recorded during non-construction hours.
			Exceedances observed at VM11 were not
9/7/2023	0.6225	N/A	construction related, it is confirmed that no
07:05, 07:45, 09:50, & 11:05	0.0225	19/11	work was being performed in the area.
			Exceedance observed at VM11 was not
9/7/2023 12:45	0.5015	N/A	construction related it is confirmed that no
<i>JAN 2023</i> 12:13	0.5015	IV/A	work was being performed in the area
			Exceedances observed at VM11 were
9/7/2023 17:15 & 22:50	0.6101	N/A	recorded during non-construction hours
			Exceedances observed at VM11 were
9/8/2023 00:40 to 05:55	0.6479	N/A	recorded during non-construction hours
			Exceedance observed at VM11 was not
0/8/2022 08:20	0.5250	27/4	exceedance observed at vivil 1 was not
9/8/2023 08.20	0.5378	N/A	work was being performed in the area
			work was being performed in the area.
0/8/2022 00 10			Exceedance observed at VM11 was not
9/8/2023 09:10	0.5508	N/A	construction related, it is confirmed that no
			work was being performed in the area.
			Exceedance observed at VM11 was not
9/8/2023 13:00	0.6656	N/A	construction related, it is confirmed that no
			work was being performed in the area.
9/8/2023	0.57	NI/A	Exceedances observed at VM11 were
15:10, 16:50, 18:00, & 21:50	0.57	IN/A	recorded during non-construction hours.
9/9/2023	0 (0(2	NT/A	Exceedances observed at VM11 were
03:25, 05:45, 13:10, 13:45	0.6963	N/A	recorded during non-construction hours.
9/10/2023	0.0120	27/4	Exceedances observed at VM11 were
11:35, 11:40, & 23:45	0.8139	N/A	recorded during non-construction hours.
9/11/2023	0.0000		Exceedances observed at VM11 were
01:20, 05:20, 06:05	0.8093	N/A	recorded during non-construction hours.
			Exceedances observed at VM11 were not
9/11/2023 09:30 & 09:45	0.7829	N/A	construction related, it is confirmed that no
	011023	1011	work was being performed in the area.
			Exceedances observed at VM11 were not
9/11/2023 13:20 & 13:45	0 5421	N/A	construction related, it is confirmed that no
	0.0 121	1011	work was being performed in the area.
			Exceedances observed at VM11 were
9/11/2023 15:50 to 18:30	1.757	N/A	recorded during non-construction hours.
9/12/2023			Exceedances observed at VM11 were
00.45 $05.20$ $05.35$ & $06.50$	0.6793	N/A	recorded during non-construction hours
00.10, 00.20, 00.00, <del>a</del> 00.00			Exceedance observed at VM11 was not
9/12/2023 07:35	0.5670	NI/A	construction related it is confirmed that no
)/12/2023 01.33	0.3079	IN/A	work was being performed in the area
			Exceedance observed at VM11 was
9/12/2023 15:35	0.5179	N/A	recorded during non-construction hours
			Exceedence cheered at VM11 was
9/13/2023 00:30	0.7171	N/A	Exceedance observed at vivil 1 was
			Fecorded during non-construction nours.
9/13/2023			Exceedances observed at VM11 were not
07:40, 07:55, 09:35, & 13:00	0.6293	N/A	construction related, it is confirmed that no
			work was being performed in the area.
9/13/2023 15:20	0 5136	$N/\Delta$	Exceedance observed at VM11 was
	0.5150	10/11	recorded during non-construction hours.
9/14/2023	0 7047	N/A	Exceedances observed at VM11 were
00:35, 05:00, & 05:15	0.7047	IN/A	recorded during non-construction hours.
9/14/2023			Exceedances observed at VM11 were not
07.05 $08.15$ $08.50$ & $11.45$	0.6724	N/A	construction related, it is confirmed that no
07.05, 00.15, 00.50, & 11.45			work was being performed in the area.
9/15/2023	0.7205	NT/ 4	Exceedances observed at VM11 were
00:25, 05:15, 05:20, & 05:50	0.0305	IN/A	recorded during non-construction hours.



9/15/2023 07:30 to 11:45	0.6343	N/A	Exceedances observed at VM11 were not construction related, it is confirmed that no work was being performed in the area.
9/15/2023 15:40	0.5312	N/A	Exceedance observed at VM11 was recorded during non-construction hours.
9/16/2023 00:40	0.5077	N/A	Exceedance observed at VM11 was recorded during non-construction hours.
9/17/2023 21:40	0.624	N/A	Exceedance observed at VM11 was recorded during non-construction hours.
9/18/2023 05:20 & 06:55	0.7463	N/A	Exceedances observed at VM11 were recorded during non-construction hours.
9/18/2023 07:40 to 13:20	1.5342	N/A	Exceedances observed at VM11 were not construction related, it is confirmed that no work was being performed in the area.
9/18/2023 18:30 to 20:45	0.9927	N/A	Exceedances observed at VM11 were recorded during non-construction hours.
9/19/2023 05:20	0.5592	N/A	Exceedance observed at VM11 was recorded during non-construction hours.
9/19/2023 21:35	0.8475	N/A	Exceedance observed at VM11 was recorded during non-construction hours.
9/20/2023 00:20	0.6029	N/A	Exceedance observed at VM11 was recorded during non-construction hours.
9/20/2023 10:15	0.5005	N/A	Exceedance observed at VM11 was not construction related, it is confirmed that no work was being performed in the area.
9/20/2023 15:45, 18:25, & 22:55	0.741	N/A	Exceedances observed at VM11 were recorded during non-construction hours.
9/21/2023 02:50	0.5101	N/A	Exceedance observed at VM11 was recorded during non-construction hours.
9/21/2023 09:40 & 10:05	0.57	N/A	Exceedances observed at VM11 were not construction related, it is confirmed that no work was being performed in the area.
9/21/2023 14:55	0.5021	N/A	Exceedance observed at VM11 was not construction related, it is confirmed that no work was being performed in the area.
9/22/2023 07:50 & 08:10	0.5322	N/A	Exceedances observed at VM11 were not construction related, it is confirmed that no work was being performed in the area.
9/22/2023 12:05	0.5306	N/A	Exceedance observed at VM11 was not construction related, it is confirmed that no work was being performed in the area.
9/22/2023 16:15 & 18:05	0.5306	N/A	Exceedances observed at VM11 were recorded during non-construction hours.
9/23/2023 00:35, 15:00, 15:45, & 16:55	0.6163	N/A	Exceedance observed at VM11 was recorded during non-construction hours.
9/24/2023 23:12	0.6144	N/A	Exceedance observed at VM11 was recorded during non-construction hours.
9/25/2023 05:35	0.5036	N/A	Exceedance observed at VM11 was recorded during non-construction hours.
9/26/2023 15:05 & 23:50	0.5638	N/A	Exceedances observed at VM11 were recorded during non-construction hours.
9/27/2023 05:20	0.534	N/A	Exceedance observed at VM11 was recorded during non-construction hours.
9/27/2023 15:45 & 16:15	0.5744	N/A	Exceedances observed at VM11 were recorded during non-construction hours.
9/28/2023 00:10 & 17:05	0.5039	N/A	Exceedances observed at VM11 were recorded during non-construction hours.
9/29/2023 05:30, 06:25, & 06:30	1.2844	N/A	Exceedances observed at VM11 were recorded during non-construction hours.
9/29/2023 07:05 to 14:01	2.2842	N/A	Exceedances observed at VM11 were not construction related, it is confirmed that no work was being performed in the area



9/29/2023 15:16 & 15:31	0.6991	N/A	Exceedances observed at VM11 were recorded during non-construction hours.
9/30/2023 00:20	0.7004	N/A	Exceedance observed at VM11 was recorded during non-construction hours.
9/10/2023 11:20, 11:35, 11:40, & 11:50	2.1805	N/A	Exceedances observed at VM12 were recorded during non-construction hours.
9/11/2023 01:20	1.0141	N/A	Exceedance observed at VM12 was recorded during non-construction hours.
9/11/2023 15:50, 15:59, & 18:15	4.1932	N/A	Exceedances observed at VM12 were recorded during non-construction hours.
9/18/2023 08:35	0.5784	N/A	Exceedance observed at VM12 was not construction related, it is confirmed that no work was being performed in the area.
9/18/2023 11:15	1.6682	N/A	Exceedance observed at VM12 was not construction related, it is confirmed that no work was being performed in the area.
9/20/2023 18:25	0.5359	N/A	Exceedance observed at VM12 was recorded during non-construction hours.
9/29/2023 06:25 & 06:30	0.8295	N/A	Exceedances observed at VM12 were recorded during non-construction hours.
9/29/2023 09:35 to 13:05	3.3088	N/A	Exceedances observed at VM12 were not construction related, it is confirmed that no work was being performed in the area.

Narrative Summary of Vibration Monitoring, Excursions and Corrective Actions:

In September 2023, four vibration monitors had recorded exceedances.

There were exceedances recorded during non-construction hours at VM6, VM11, and VM12. There were isolated events recorded at VM6 and VM7, possibly due to non-construction related activities, associated with resident's activities. No corrective actions were required at this time.

The exceedances recorded at VM11 on September 1<sup>st</sup> were due to rock chopping with an excavator hoe ram. The intensity of the hoe ram on the excavator was lower post events.

The rest of the exceedances recorded at VM11 and VM12 were non-construction related. The event times when the exceedances were recorded were reviewed by the contractor, it is confirmed that no work was being performed in the area during these event periods. No corrective action was required at these times.



AECOM-Hill JV 10/26/2023

4) Community Vibration Blasting Monitoring Monthly Summary				
Units: inches per second (in/sec)				
Number of Workdays in a Month	Number of Vibration Monitoring Days in a Month	Number of Days with Vibration Levels above Action Levels by Month	Comments	
20	30	0	No vibration exceedance was observed in September.	
<b>Community Vibration M</b> Action Level = 2.0 in/sec Action Level = 4.0 in/se Action Level = 12.0 in/s	onitoring Excursions and for VMs install at Concor c for VMs install at 142 <sup>nd</sup> ec for VMs install on all ι	d <b>Corrective Actions</b> d Ave, 141 <sup>st</sup> St, and So St underground utilities	outhern Blvd.	
Date: Time	Maximum Vibration Level before Corrective Action (in/sec)	Maximum Vibration Level after Corrective Action (in/sec)	Corrective Action	
9/6/2023 11:38	0.6054	N/A	Vibration reading over 0.5 in/s was observed at VM11. Per blast plan, the peak particle velocity allowed for all underground utilities caused by blasting is 12 in/s. The reading is within the limit. No corrective action was required at this time.	
9/7/2023 11:40	0.5424	N/A	Vibration reading over 0.5 in/s was observed at VM11. Per blast plan, the peak particle velocity allowed for all underground utilities caused by blasting is 12 in/s. The reading is within the limit. No corrective action was required at this time.	
9/8/2023 08:45	0.5821	N/A	Vibration reading over 0.5 in/s was observed at VM11. Per blast plan, the peak particle velocity allowed for all underground utilities caused by blasting is 12 in/s. The reading is within the limit. No corrective action was required at this time.	
9/8/2023 11:35	0.5561	N/A	Vibration reading over 0.5 in/s was observed at VM11. Per blast plan, the peak particle velocity allowed for all underground utilities caused by blasting is 12 in/s. The reading is within the limit. No corrective action was required at this time.	
9/11/2023 11:55	0.5908	N/A	Vibration reading over 0.5 in/s was observed at VM11. Per blast plan, the peak particle velocity allowed for all underground utilities caused by blasting is 12 in/s. The reading is within the limit. No corrective action was required at this time.	
9/19/2023 09:56	0.7097	N/A	Vibration reading over 0.5 in/s was observed at VM11. Per blast plan, the peak particle velocity allowed for all underground utilities caused by blasting is 12 in/s. The reading is within the limit. No corrective action was required at this time.	
9/19/2023 12:35	0.9387	N/A	Vibration reading over 0.5 in/s was observed at VM11. Per blast plan, the peak particle velocity allowed for all underground utilities caused by blasting is	



AECOM-Hill JV 10/26/2023

			12 in/s. The reading is within the limit. No
			Vibration reading over 0.5 in/s was
			observed at VM11. Per blast plan, the peak
9/20/2023 09:55	1 2841	N/A	particle velocity allowed for all
7/20/2023 07:33	1.2841	IN/A	underground utilities caused by blasting is
			12 in/s. The reading is within the limit. No
			Vibration reading over 0.5 in/a was
			vibration reading over 0.5 m/s was observed at VM11 Per blast plan, the peak
			particle velocity allowed for all
9/21/2023 10:40	1.218	N/A	underground utilities caused by blasting is
			12 in/s. The reading is within the limit. No
			corrective action was required at this time.
			Vibration reading over 0.5 in/s was
			observed at VM11. Per blast plan, the peak
9/22/2023 09:40	0.9173	N/A	particle velocity allowed for all
			12  in/s The reading is within the limit. No
			corrective action was required at this time.
			Vibration reading over 0.5 in/s was
			observed at VM11. Per blast plan, the peak
9/22/2023 12:30	0.7662	NT/A	particle velocity allowed for all
7/22/2023 12:30	0.7002	IN/A	underground utilities caused by blasting is
			12 in/s. The reading is within the limit. No
			Vibration reading over 0.5 in/a was
			observed at VM11 Per blast plan the peak
			particle velocity allowed for all
9/25/2023 10:47	0.7084	N/A	underground utilities caused by blasting is
			12 in/s. The reading is within the limit. No
			corrective action was required at this time.
			Vibration reading over 0.5 in/s was
			observed at VM11. Per blast plan, the peak
9/26/2023 09:07	0.9669	N/A	underground utilities caused by blasting is
			12  in/s. The reading is within the limit. No
			corrective action was required at this time.
			Vibration reading over 0.5 in/s was
			observed at VM11. Per blast plan, the peak
9/26/2023 13:25	0.9539	N/A	particle velocity allowed for all
	0.9339	1 1/2 1	underground utilities caused by blasting is
			12 In/s. The reading is within the limit. No
			Vibration reading over 0.5 in/s was
			observed at VM11. Per blast plan, the peak
0/27/2022 10:20	0.77.70		particle velocity allowed for all
9/27/2023 10:20	0.6762	N/A	underground utilities caused by blasting is
			12 in/s. The reading is within the limit. No
			corrective action was required at this time.
			Vibration reading over 0.5 in/s was
			particle velocity allowed for all
9/27/2023 14:20	0.8195	N/A	underground utilities caused by blasting is
			12  in/s. The reading is within the limit. No
			corrective action was required at this time.
			Vibration reading over 0.5 in/s was
	0.53	N/A	observed at VM12. Per blast plan, the peak
9/5/2023 10:50			particle velocity allowed for all
		- 0.4 4	underground utilities caused by blasting is
			corrective action was required at this time



AECOM-Hill JV	
10/26/2023	

9/6/2023 11:40	0.916	N/A	Vibration reading over 0.5 in/s was observed at VM12. Per blast plan, the peak particle velocity allowed for all underground utilities caused by blasting is 12 in/s. The reading is within the limit. No corrective action was required at this time.
9/7/2023 08:15	0.5074	N/A	Vibration reading over 0.5 in/s was observed at VM12. Per blast plan, the peak particle velocity allowed for all underground utilities caused by blasting is 12 in/s. The reading is within the limit. No corrective action was required at this time.
9/7/2023 11:40	0.6606	N/A	Vibration reading over 0.5 in/s was observed at VM12. Per blast plan, the peak particle velocity allowed for all underground utilities caused by blasting is 12 in/s. The reading is within the limit. No corrective action was required at this time.
9/8/2023 08:50	0.5449	N/A	Vibration reading over 0.5 in/s was observed at VM12. Per blast plan, the peak particle velocity allowed for all underground utilities caused by blasting is 12 in/s. The reading is within the limit. No corrective action was required at this time.
9/8/2023 11:35	0.6597	N/A	Vibration reading over 0.5 in/s was observed at VM12. Per blast plan, the peak particle velocity allowed for all underground utilities caused by blasting is 12 in/s. The reading is within the limit. No corrective action was required at this time.
9/11/2023 11:55	0.7069	N/A	Vibration reading over 0.5 in/s was observed at VM12. Per blast plan, the peak particle velocity allowed for all underground utilities caused by blasting is 12 in/s. The reading is within the limit. No corrective action was required at this time.
9/18/2023 10:05	0.5437	N/A	Vibration reading over 0.5 in/s was observed at VM12. Per blast plan, the peak particle velocity allowed for all underground utilities caused by blasting is 12 in/s. The reading is within the limit. No corrective action was required at this time.
9/18/2023 13:20	0.6479	N/A	Vibration reading over 0.5 in/s was observed at VM12. Per blast plan, the peak particle velocity allowed for all underground utilities caused by blasting is 12 in/s. The reading is within the limit. No corrective action was required at this time.
9/19/2023 09:55	1.0271	N/A	Vibration reading over 0.5 in/s was observed at VM12. Per blast plan, the peak particle velocity allowed for all underground utilities caused by blasting is 12 in/s. The reading is within the limit. No corrective action was required at this time.
9/19/2023 12:35	1.1574	N/A	Vibration reading over 0.5 in/s was observed at VM12. Per blast plan, the peak particle velocity allowed for all underground utilities caused by blasting is 12 in/s. The reading is within the limit. No corrective action was required at this time.
9/20/2023 09:55	1.6766	N/A	Vibration reading over 0.5 in/s was observed at VM12. Per blast plan, the peak particle velocity allowed for all



```
AECOM-Hill JV
```

10/26/2023

			underground utilities caused by blasting is 12 in/s. The reading is within the limit. No corrective action was required at this time.
9/20/2023 12:15	0.5902	N/A	Vibration reading over 0.5 in/s was observed at VM12. Per blast plan, the peak particle velocity allowed for all underground utilities caused by blasting is 12 in/s. The reading is within the limit. No corrective action was required at this time.
9/21/2023 10:40	1.4913	N/A	Vibration reading over 0.5 in/s was observed at VM12. Per blast plan, the peak particle velocity allowed for all underground utilities caused by blasting is 12 in/s. The reading is within the limit. No corrective action was required at this time.
9/21/2023 13:40	0.764	N/A	Vibration reading over 0.5 in/s was observed at VM12. Per blast plan, the peak particle velocity allowed for all underground utilities caused by blasting is 12 in/s. The reading is within the limit. No corrective action was required at this time.
9/22/2023 09:40	0.9815	N/A	Vibration reading over 0.5 in/s was observed at VM12. Per blast plan, the peak particle velocity allowed for all underground utilities caused by blasting is 12 in/s. The reading is within the limit. No corrective action was required at this time.
9/22/2023 12:30	1.0836	N/A	Vibration reading over 0.5 in/s was observed at VM12. Per blast plan, the peak particle velocity allowed for all underground utilities caused by blasting is 12 in/s. The reading is within the limit. No corrective action was required at this time.
9/25/2023 10:47	0.6516	N/A	Vibration reading over 0.5 in/s was observed at VM12. Per blast plan, the peak particle velocity allowed for all underground utilities caused by blasting is 12 in/s. The reading is within the limit. No corrective action was required at this time.
9/26/2023 09:07	1.2384	N/A	Vibration reading over 0.5 in/s was observed at VM12. Per blast plan, the peak particle velocity allowed for all underground utilities caused by blasting is 12 in/s. The reading is within the limit. No corrective action was required at this time.
9/26/2023 13:26	1.2896	N/A	Vibration reading over 0.5 in/s was observed at VM12. Per blast plan, the peak particle velocity allowed for all underground utilities caused by blasting is 12 in/s. The reading is within the limit. No corrective action was required at this time.
9/27/2023 10:20	1.2037	N/A	Vibration reading over 0.5 in/s was observed at VM12. Per blast plan, the peak particle velocity allowed for all underground utilities caused by blasting is 12 in/s. The reading is within the limit. No corrective action was required at this time.
9/27/2023 14:20	1.564	N/A	Vibration reading over 0.5 in/s was observed at VM12. Per blast plan, the peak particle velocity allowed for all underground utilities caused by blasting is 12 in/s. The reading is within the limit. No corrective action was required at this time.



Narrative Summary of Vibration Monitoring, Excursions and Corrective Actions:

In September 2023, no vibration monitors had recorded exceedance that's over the action level for blasting.

Blasting activities caused thirty-eight readings over 0.5 in/s at VM11 and VM12. Per the blast plan, the peak particle velocity allowed for all underground utilities caused by blasting is 12 in/s. All these vibration events are within the limit. No corrective action was required at these times.

Four portable vibration monitors for blasting monitoring were deployed at the following locations: BVM-A was installed at location no. 10, BVM-B at location no. 1, BVM-C at location no. 9, and BVM-D at location no. 6 on September 1<sup>st</sup>, September 5<sup>th</sup> to September 8<sup>th</sup>, and September 11<sup>th</sup>.

BVM-A was installed at location no. 11, BVM-B at location no. 2, BVM-C at location no. 8, and BVM-D at location no. 5 on September 12<sup>th</sup>, September 14<sup>th</sup>, September 18<sup>th</sup> to September 22<sup>nd</sup>, and September 25<sup>th</sup> to September 27<sup>th</sup>.

#### ATTACHMENTS:

- 1 Include one map of monitoring station/locations
- 2 Include Data Plots
- 3 Include Baseline Reference

**Blasting - Vibration Monitor Locations** 

E 142nd St

**Plan North** 

353

343

333

-

st St

# Attachments

# **Environmental Monitoring The Bronx**





Air Monitoring Station (DM) Noise Monitoring Station (NM) Blasting - Vibration Monitor (VM)







Exceedance level: 1 in/sec Warning level: 0.5 in/sec

C2202-VM5 Transverse C2202-VM5,2 Vertical C2202-VM5,3 Longitudinal





Exceedance level: 1 in/sec Warning level: 0.5 in/sec

C2202-VM6 Transverse C2202-VM6,2 Vertical C2202-VM6,3 Longitudinal





Exceedance level: 1 in/sec Warning level: 0.5 in/sec

C2202-VM7 Longitudinal C2202-VM7,2 Transverse C2202-VM7,3 Vertical





Exceedance level: 1 in/sec Warning level: 0.5 in/sec

C2202-VM8A Longitudinal C2202-VM8A,2 Transverse C2202-VM8A,3 Vertical





Exceedance level: 1 in/sec Warning level: 0.5 in/sec

C2202-VM11 Transverse C2202-VM11,2 Vertical C2202-VM11,3 Longitudinal





Exceedance level: 1 in/sec Warning level: 0.5 in/sec

C2202-VM12 Transverse C2202-VM12,2 Vertical C2202-VM12,3 Longitudinal





Exceedance level: 2 in/sec 9/1/2023-9/11/2023 at location# 10 9/12/2023-9/30/2023 at location# 11

C2202-BVM-A Transverse C2202-BVM-A,3 Vertical C2202-BVM-A,5 Longitudinal





Exceedance level: 4 in/sec 9/1/2023-9/11/2023 at location# 1 9/12/2023-9/30/2023 at location# 2

C2202-BVM-B Transverse C2202-BVM-B,3 Vertical C2202-BVM-B,5 Longitudinal





Exceedance level: 2 in/sec 8/31/2023-9/11/2023 at location# 9 9/12/2023-9/30/2023 at location# 8

C2202-BVM-C Transverse C2202-BVM-C,3 Vertical C2202-BVM-C,5 Longitudinal





Exceedance level: 2 in/sec 8/31/2023-9/11/2023 at location# 6 9/12/2023-9/30/2023 at location# 5

C2202-BVM-D Transverse C2202-BVM-D,3 Vertical C2202-BVM-D,5 Longitudinal





Exceedance level: 1 in/sec Warning level: 0.5 in/sec

C2202-VM1 Transverse C2202-VM1,2 Vertical C2202-VM1,3 Longitudinal





Exceedance level: 1 in/sec Warning level: 0.5 in/sec

C2202-VM2 Transverse C2202-VM2,2 Vertical C2202-VM2,3 Longitudinal





Exceedance level: 1 in/sec Warning level: 0.5 in/sec

C2202-VM3 Transverse C2202-VM3,2 Vertical C2202-VM3,3 Longitudinal





Exceedance level: 1 in/sec Warning level: 0.5 in/sec

C2202-VM4 Transverse C2202-VM4,2 Vertical C2202-VM4,3 Longitudinal

![](_page_29_Picture_4.jpeg)

![](_page_30_Picture_1.jpeg)

Exceedance level: 1 in/sec Warning level: 0.5 in/sec

C2202-VM5 Transverse C2202-VM5,2 Vertical C2202-VM5,3 Longitudinal

![](_page_30_Picture_4.jpeg)

![](_page_31_Picture_1.jpeg)

Exceedance level: 1 in/sec Warning level: 0.5 in/sec

C2202-VM6 Transverse C2202-VM6,2 Vertical C2202-VM6,3 Longitudinal

![](_page_31_Picture_4.jpeg)

![](_page_32_Picture_1.jpeg)

Exceedance level: 1 in/sec Warning level: 0.5 in/sec

C2202-VM7 Longitudinal C2202-VM7,2 Transverse C2202-VM7,3 Vertical

![](_page_32_Picture_4.jpeg)

![](_page_33_Picture_1.jpeg)

Exceedance level: 1 in/sec Warning level: 0.5 in/sec

C2202-VM8 Longitudinal C2202-VM8,2 Transverse C2202-VM8,3 Vertical

![](_page_33_Picture_4.jpeg)

![](_page_34_Picture_1.jpeg)

Exceedance level: 1 in/sec Warning level: 0.5 in/sec

C2202-VM9 Longitudinal C2202-VM9,2 Transverse C2202-VM9,3 Vertical

![](_page_34_Picture_4.jpeg)

![](_page_35_Picture_1.jpeg)

Exceedance level: 1 in/sec Warning level: 0.5 in/sec

C2202-VM10 Longitudinal C2202-VM10,2 Transverse C2202-VM10,3 Vertical

![](_page_35_Picture_4.jpeg)

![](_page_36_Picture_1.jpeg)

Exceedance level: 1 in/sec Warning level: 0.5 in/sec

C2202-VM11 Transverse C2202-VM11,2 Vertical C2202-VM11,3 Longitudinal

![](_page_36_Picture_4.jpeg)

![](_page_37_Picture_1.jpeg)

Exceedance level: 1 in/sec Warning level: 0.5 in/sec

C2202-VM12 Transverse C2202-VM12,2 Vertical C2202-VM12,3 Longitudinal

![](_page_37_Picture_4.jpeg)